

# MONTHLY SAFETY ACTIVITIES

October 1, 2020 to October 30, 2020

COVID-19 workplace safety considerations are still being executed at NID.

Training classes were revised to ensure social distancing guidelines were met; logistical coordination with departments was needed to ensure disinfectant was available to all, and ICS safety recommendations & activities were executed.

## SITE VISIT

- Hydroelectric Department: Dutch Flat Penstock Intake, went out to access for a pre-scheduled confined space entry
- Hydroelectric Department: Dutch Flat Powerhouse, evaluate the scheduled outage
- Hydroelectric Department: Rollins Powerhouse, evaluate the scheduled outage
- Maintenance Department: Bear Valley inspection with Evan Parks, Maintenance Supervisor
- Maintenance Department: emergency repair on Sandra Ct.
- Recreation Department: restocking first aid kits
- Placer Maintenance Department: working with traffic control
- Placer Maintenance Department: building headwall structure



Placer Maintenance Department, headwall structure installation, Fruitvale Road

## TRAINING CLASSES

- Maintenance Department: New orientation training for a temporary utility worker
- Maintenance Department: Heavy equipment training
- Finance Department: New orientation training
- Hydroelectric Department: Confined space entry with rescue team at Dutch Flat Penstock Intake
- Survey Department: Fall protection at Saw Mill

## ADMINISTRATION

- Accident report: broken side mirror: Placer Maintenance Department
- Reviewed incident report regarding broken bumper: Water Treatment Department
- Reviewed incident report regarding a bee sting: Maintenance Department
- Accident report: backed into a tree, side door, side mirror, and door handle damaged: Operations Department
- Meeting: with Greg Jones, Interim General Manager, regarding District claims
- Complete claims for the District
- Hydroelectric Department: Rollins Powerhouse, docking station, and gas monitor calibration
- Meeting: with Paul Fisher, CWP. Glatfelter Insurance Company regarding the District Risks Analysis
- District walkthrough Risk Inspection with Glatfelter Insurance at the Elizabeth George Water Treatment Plant
- District walkthrough Risk Inspection with Glatfelter Insurance at the Lake of the Pines Water Treatment Plant
- District walkthrough Risk Inspection with Glatfelter Insurance at the Grass Valley Main Yard
- Post District Risk Assessment from Glatfelter: Exit sign stickers were placed at the following locations: Placer Maintenance Yard, Lake of the Pines Water Treatment Plant, and Grass Valley Yard buildings-after remodels were done to these buildings, exit signs had not been replaced.
- Develop Safety Data Sheet Books for Operations Department (6 books made)
- Develop Safety Data Sheet Books for Maintenance Department (2 books made)
- Six-month inspection walkthrough from Beam Fire Alarm
- Target Solutions: continue tracking employee trainings and certifications
- Heavy Equipment training, tracking employees for record-keeping